

Commonwealth of Massachusetts

Town of Douglas

**Douglas
Tree Warden**

Public Shade Tree Removal Permit

This Shade Tree Removal Permit is hereby issued in accordance with Massachusetts General Laws, Chapter 87, Public Shade Tree Law, Section 3 (Cutting of Public Shade Trees; Hearing; Damages). The applicant is National Grid, Hazard Tree Mitigation Program, c/o Joan Callahan, 939 Southbridge Street, Worcester, MA 01610.

The program included a tree-by-tree hazard assessment of the main three-phase lines in Douglas. Town and municipal-owned trees that are hazardous and/or prone to failure, pose a threat to public safety and endanger the reliability of the main distribution lines along these routes, were identified for removal or pruning in an effort to reduce or eliminate their risk of failure.

Two hundred eighty-four (284) town-owned trees were identified by National Grid arborists for removal and fourteen (14) for pruning.

I hereby grant permission to National Grid to remove or prune trees per specific list attached to this permit.

APPROVAL:

John Furno
Tree Warden

Date _____

Ownership Key:
 C/T = City or Town
 P = Private
 S = State
 M = Municipal

Town of Douglas (Town and Municipal-owned Trees)

nationalgrid

Town of Douglas Enhanced Vegetation Management Tree Removal/Trim List Circuit #: 320W2										GYPSY MOTH DAMAGE - INSERT		Work Proposed
Count	Site ID	Street Name	Pole #	House #	Location	Owner	Dia.	Species	# Stem	Defect Condition		
1	DC64	Charles St	2-3	29		M	12	Maple	2	Lean, weight to line, heavy dieback		Remove
2	DC101	SE Main St	4-5	Lot		M	8	Maple		Dead		Remove
3	DC101	SE Main St	4-5	Lot		M	15	Maple		Lean, weight over line, cavity widecay		Remove
4	PJ05	West St	10-11	Lot		M	10	N. Maple		Proximity/ topped the past		Remove
5	PJ05	West St	10-11	Lot		M	12	Pine		Crown decline		Remove
6	PJ05	West St	10-11	Lot		M	14	Pine		Dead		Remove
7	PJ05	West St	10-11	Lot		M	13	Pine		Dead		Remove
8	PJ05	West St	10-11	Lot		M	14	Pine		Crown decline		Remove
9	PJ05	West St	10-11	Lot		M	15	Pine		Dead		Remove
10	PJ05	West St	10-11	Lot		M	12	Pine		Dead		Remove
11	PJ05	West St	10-11	Lot		M	14	Pine		Dead		Remove
12	PJ05	West St	10-11	Lot		M	15	Pine		Dead		Remove
13	PJ05	West St	10-11	Lot		M	14	Pine		Dead		Remove
14	PJ05	West St	10-11	Lot		M	16	Pine		Dead		Remove
15	PJ05	West St	11-12	Lot		M	47	Pine		Proximity/ poor structure		Remove
16	PJ05	West St	11-12	Lot		M	8	Pine		Proximity		Remove
17	PJ05	West St	11-12	Lot		M	15	Pine		Proximity		Remove
18	PJ05	West St	11-12	Lot		M	11	Pine		Proximity		Remove
19	PJ05	West St	11-12	Lot		M	14	Pine		Proximity		Remove
20	PJ05	West St	11-12	Lot		M	20	Pine		Proximity		Remove
21	PJ05	West St	12-13	Lot		M	14	Pine		Proximity		Remove
22	PJ05	West St	12-13	Lot		M	8	Poplar		Proximity/ dead		Remove
23	PJ05	West St	13-14	Lot		M	36	Oak		Lean to lines/ dead leads/ base damage		Remove
24	PJ05	West St	14-14.1	Lot	AF	M	32	Oak		Proximity/ dead		Remove
25	PJ05	West St	14-1-14.2	Lot		M	17	Oak		Proximity/ dead leads		Remove
26	PJ05	West St	14-1-14.2	Lot		M	20	Pine		Proximity		Remove
27	PJ05	West St	14-1-14.2	Lot		M	16	Oak		Dead		Remove
28	PJ05	West St	14-1-14.2	Lot		M	12	Pine		Proximity/ dead		Remove
29	PJ05	West St	14-1-14.2	Lot		M	19	Oak		Proximity/ dead leads		Remove
30	PJ05	West St	14-1-14.2	Lot		M	8	Pine		Dead		Remove
31	PJ05	West St	14-1-14.2	Lot	AF	M	8	Oak		Poor anchorage		Remove
32	PJ05	West St	14-1-14.2	Lot	AF	M	12	Pine		Poor anchorage		Remove
33	PJ05	West St	14-1-14.2	Lot	AF	M	12	Pine		Proximity/ dead leads		Remove
34	PJ05	West St	14-2-14.3	Lot		M	14	Oak		Proximity/ dead leads		Remove
35	PJ05	West St	14-2-14.3	Lot		M	12	Oak		Proximity		Remove
36	PJ05	West St	14-2-14.3	Lot		M	22	Pine		Proximity		Remove
37	PJ05	West St	14-2-14.3	Lot		M	17	Pine		Proximity		Remove
38	PJ05	West St	14-2-14.3	Lot	AF	M	16	Pine		Proximity/ dead		Remove
39	PJ05	West St	14-2-14.3	Lot		M	18	Oak		Proximity/ lean to lines		Remove
40	PJ05	West St	14-3-14.4	Lot		M	10	Oak		Proximity/ lean to lines		Remove
41	PJ05	West St	14-3-14.4	Lot		M	15	Oak		Proximity/ topped in past		Remove
42	PJ05	West St	14-3-14.4	Lot		M	14	Pine				Remove

Ownership Key:
 C/T = City or Town
 P = Private
 S = State
 M = Municipal

Town of Douglas (Town and Municipal-owned Trees)

nationalgrid

Town of Douglas Enhanced Vegetation Management Tree Removal/Trim List Circuit #: 320W2										GYPSY MOTH DAMAGE - INSERT		Work Proposed
Count	Site ID	Street Name	Pole #	House #	Location	Owner	Dia.	Species	# Stem	Defect Condition		
43	PJ05	West St	14.3-14.4	Lot		M	24	Pine		Proximity		Remove
44	PJ05	West St	14.3-14.4	Lot		M	16	Oak		Proximity		Remove
45	MD11	Franklin St	26-27	lot		M	16	Pine		Proximity		Remove
46	MD11	Franklin St	26-27	lot		M	18	Oak		Proximity		Remove
47	MD11	Franklin St	26-27	lot		M	18	Oak		Proximity		Remove
48	MD12	Franklin St	26-27	lot		M	24	Pine		Proximity		Remove
49	DC44	Gilboa St	57-56	Lot		T	8	Oak		Proximity	Y	Remove
50	DC44	Gilboa St	55-54	Lot		T	10	Pine		Proximity		Remove
51	DC44	Gilboa St	51/50-50	Lot		T	20	Maple		Lean, weight over lines, proximity		Remove
52	DC44	Gilboa St	50	Lot	AP	T	24	Maple		Proximity, underlines		Remove
53	DC44	Gilboa St	50-49	Lot		T	18	Maple		Under lines, heavy dieback		Remove
54	DC44	Gilboa St	50-59	Lot		T	16	Maple		Under lines, heavy dieback		Remove
55	DC45	Gilboa St	43-42	Lot		T	26	Maple		Dieback, proximity		Remove
56	DC45	Gilboa St	42-40	Lot		T	8	Maple		Lean, weight over lines, poor structure		Remove
57	DC45	Gilboa St	40-39	Lot		T	10	Pine		Weight to line, less than 30% crown		Remove
58	DC45	Gilboa St	40-39	Lot		T	22	Pine		Thin crown, less than 30% crown		Remove
59	DC45	Gilboa St	40-39	Lot		T	24	Pine		Lean, weight over line, proximity, less than 50% crown		Remove
60	DC45	Gilboa St	40-39	Lot		T	10	Pine		Weight to line, less than 30% crown		Remove
61	DC45	Gilboa St	40-39	Lot		T	16	Pine		Weight over line, less than 50% crown		Remove
62	DC45	Gilboa St	40-39	Lot		T	25	Pine		Weight over line, proximity		Remove
63	DC45	Gilboa St	40-39	Lot		T	18	Pine		Lean, weight over line, proximity		Remove
64	DC45	Gilboa St	39-38	Lot		T	13	Pine		Weight to line, less than 30% crown		Remove
65	DC45	Gilboa St	39-38	Lot		T	10	Birch		Weight to line, less than 30% crown		Remove
66	DC45	Gilboa St	39-38	Lot		T	10	Pine		Weight to line, less than 30% crown		Remove
67	DC45	Gilboa St	39-38	Lot		T	24	Pine		Lean, weight over line, proximity		Remove
68	DC45	Gilboa St	38-37	Lot		T	12	Maple		Weight over line, less than 50% crown		Remove
69	DC48A	Gilboa St	27-26	56		T	15	Oak		Weight over lines, Proximity	Y	Remove
70	DC65	Charles St	3	25	AP	T	10	Spruce		Proximity		Remove
71	DC65	Charles St	3	25	AP	T		Maple		Lean, weight to line, heavy dieback		Remove
72	DC66	Charles St	5-6	Lot		T	24	Ash		Weight over lines, dieback		Remove

Ownership Key:
 C/T = City or Town
 P = Private
 S = State
 M = Municipal

Town of Douglas (Town and Municipal-owned Trees)

nationalgrid

Town of Douglas Enhanced Vegetation Management Tree Removal/Trim List Circuit #: 320W2										GYPSY MOTH DAMAGE - INSERT		Work Proposed
Count	Site ID	Street Name	Pole #	House #	Location	Owner	Dia.	Species	# Stem	Defect Condition		
73	DC66	Charles St	6-7	Lot		T	12	Apple	2	Weight over lines, dieback		Remove
74	DC66	Charles St	6-7	Lot		T	12	Apple	2	Weight over lines, dieback		Remove
75	DC67	Charles St	5	18/20	AP	T	20	Maple		Weight over lines, proximity		Remove
76	DC68	Charles St	7-8	11		T	11	Maple		Lean, weight over line, proximity		Remove
77	DC68	Charles St	7-8	9		T	8	Maple		Under lines, proximity		Remove
78	DC69	Charles St	7-8	9		T	15	Maple		Under lines, proximity		Remove
79	DC69	Charles St	7-8	9		T	10	Maple		Under lines, proximity		Remove
80	DC74	Depot Rd	14-15	Lot		T	12	Maple		Under lines, dieback		Remove
81	DC74	Depot Rd	14-15	Lot		T	8	Maple		Under lines, proximity		Remove
82	DC75	Depot Rd	14-15	34		T	8	Maple		Under lines		Remove
83	DC75	Depot Rd	14-15	34		T	20	Maple	2	Dieback, proximity		Remove
84	DC81	Main St	38-41	Lot		T	20	Pine		Under lines, fungal bodies present		Remove
85	DC81	Main St	38-41	Lot		T	8	Maple		Lean, weight to lines, dieback		Remove
86	DC83	Main St	41-42	Lot		T	16	Pine		Lean, weight to line, dieback		Remove
87	DC83	Main St	41-42	Lot		T	12	Pine	2	Lean, weight to line, dieback		Remove
88	DC83	Main St	41-42	Lot		T	6	Pine		Dead		Remove
89	DC83	Main St	42	Lot		T	10	Pine		Dead		Remove
90	DC83	Main St	42-43	Lot		T	20	Pine		Lean, weight to line, dieback		Remove
91	DC83	Main St	42-43	Lot		T	13	Pine		Dead		Remove
92	DC83	Main St	42-43	Lot		T	17	Pine		Under lines		Remove
93	DC83	Main St	42-43	Lot		T	15	Maple		Lean, weight to line		Remove
94	DC84	Main St	44-45	Lot		T	12	Maple	2	Dead		Remove
95	DC84	Main St	44-45	Lot		T	13	Pine		Underlines		Remove
96	DC84	Main St	44-45	Lot		T	12	Pine		Dead		Remove
97	DC84	Main St	44-45	Lot		T	10	Pine		Lean, weight to lines		Remove
98	DC84	Main St	44-45	Lot		T	10	Pine		Under lines		Remove
99	DC84	Main St	45	Lot	AP	T	8	Pine		Under lines		Remove
100	DC84	Main St	45-50	Lot		T	18	Maple		Weight over line, cavity w/decay		Remove
101	DC84	Main St	45-50	Lot		T	28	Maple		Weight over line, heavy vines		Remove
102	DC85	Main St	45-50	Lot	AF	T	24	Oak		Heavy lean towards lines, signs of eternal decay	Y	Remove
103	DC87	Main St	51-52	Lot	AF	T	17	Pine		Lean, weight to line, dieback		Remove
104	DC87	Main St	51-52	Lot	AF	T	25	Ash		Lean, weight to line, dieback		Remove
105	DC92	Main St	83-84	46		T	22	Maple	2	Lean, weight over lines, cavity w/decay		Remove

Ownership Key:
C/T = City or Town
P = Private
S = State
M = Municipal

Town of Douglas (Town and Municipal-owned Trees)

nationalgrid

Town of Douglas Enhanced Vegetation Management Tree Removal/Trim List Circuit #: 320W2										GYPSY MOTH DAMAGE - INSERT		Work Proposed	
Count	Site ID	Street Name	Pole #	House #	Location	Owner	Dia.	Species	# Stem	Defect Condition	Y		
106	DC96	Main St	99-100	Lot		T	24	Maple		Lean, weight over line, dieback, cavity w/decay Remove 12" lowest limb over line			Remove
107	DC96	Main St	100-101	Lot		T	32	Oak			Y		Trim
108	DC97	Main St	100-101	Lot		T	14	Maple	4	Lean, weight to line, dieback Weight over line, dieback, less than 50% crown			Remove
109	DC97	Main St	100-101	Lot		T	28	Ash		Lean, weight over line, cavity w/decay			Remove
110	DC98	Main St	106-107	Lot		T	25	Maple		Under lines			Remove
111	DC98	Main St	106-107	Lot		T	18	Maple		Under lines			Remove
112	DC100	SE Main St	2-3	Lot		T	25	Ash	2	Dead			Remove
113	DC100	SE Main St	3-4	Lot		T	20	Ash	2	Dead			Remove
114	DC105	SE Main St	10-11	38		T	22	Oak		Dead	Y		Remove
115	DC108	SE Main St	14-15	46		T	8	Pine		Under lines			Remove
116	DC109	SE Main St	14-15	54		T	28	Oak		Lean, weight over line, remove 15" limb over line	Y		Trim
117	DC109	SE Main St	14-15	54		T	28	Oak		Multiple cavities w/decay	Y		Remove
118	DC109	SE Main St	14-15	54		T	12	Elm	2	Lean, weight over line, cavity with decay			Remove
119	DC109	SE Main St	14-15	54		T	24	Ash		Lean, weight over line, dieback			Remove
120	DC110	SE Main St	16-17	56		T	24	Oak		Lean, weight over line, cavity with decay	Y		Remove
121	DC111	SE Main St	17-18	58		T	10	Maple		Lean, weight over line, cavity with decay			Remove
122	DC111	SE Main St	17-18	58		T	10	Maple		Lean, weight over line, cavity with decay			Remove
123	DC112	SE Main St	18-19	66		T	15	Oak		Dead	Y		Remove
124	DC112	SE Main St	18-19	66		T	10	Birch	4	Lean, weight over line, almost dead			Remove
125	DC112	SE Main St	18-19	66		T	24	Oak		Remove 8" lowest limb over line	Y		Trim
126	DC112	SE Main St	18-19	66		T	14	Poplar		Almost dead			Remove
127	DC112	SE Main St	18-19	66		T	10	Birch		Lean, weight over line, almost dead			Remove
128	DC112	SE Main St	18-19	66		T	14	Birch		Lean, weight over line, almost dead			Remove
129	DC113	SE Main St	20-21	72		T	24	Maple		Remove 8" limb over lines			Trim
130	DC114	SE Main St	21-22	80		T	8	Maple		Almost dead			Remove
131	DC114	SE Main St	21-22	80		T	8	Birch		Almost dead			Remove
132	DC114	SE Main St	21-22	80		T	20	Oak		Dead	Y		Remove
133	DC116	SE Main St	23-24	83		T	18	Maple		Dead	Y		Remove
134	DC116	SE Main St	23-24	83		T	16	Oak		Dead	Y		Remove
135	DC117	SE Main St	23-24	86		T	24	Oak		Dead	Y		Remove

Ownership Key:
 C/T = City or Town
 P = Private
 S = State
 M = Municipal

Town of Douglas (Town and Municipal-owned Trees)

nationalgrid

Town of Douglas Enhanced Vegetation Management Tree Removal/Trim List Circuit #: 320W2												
Count	Site ID	Street Name	Pole #	House #	Location	Owner	Dia.	Species	# Stem	Defect Condition	GYPSY MOTH DAMAGE - INSERT	Work Proposed
136	DC117	SE Main St	23-24	86		T	24	Oak		Dead	Y	Remove
137	DC118	SE Main St	26-27	96		T	24	Oak		Remove 8" limb over line	Y	Trim
138	DC118	SE Main St	26-27	96		T	15	Birch		Lean, weight over line, cavity w/decay		Remove
139	DC118	SE Main St	26-27	96		T	16	Birch		Lean, weight over line, cavity w/decay		Remove
140	DC121	SE Main St	30-31	106		T	16	Oak		Lean, weight over line, cavity w/decay	Y	Remove
141	DC124	SE Main St	35-36	120		T	21	Oak		Dead	Y	Remove
142	DC124	SE Main St	35-36	120		T	18	Oak		Almost dead cavity/w decay	Y	Remove
143	DC125	SE Main St	37-38	122		T	8	Oak		Dead	Y	Remove
144	DC126	SE Main St	37-38	125		T	11	Birch		Almost dead cavity/w decay		Remove
145	DC126	SE Main St	37-38	125		T	11	Birch		Almost dead cavity/w decay		Remove
146	DC127	SE Main St	39-40	129		T	20	Oak		Dead	Y	Remove
147	DC127	SE Main St	39-40	129		T	18	Oak		Dead	Y	Remove
148	DC128	SE Main St	39-40	126		T	24	Oak		Dead	Y	Remove
149	DC129	SE Main St	40-41	134		T	8	Ash	2	Lean, weight over lines, dieback		Remove
150	DC130	SE Main St	40-41	135	AF	T	12	Ash		Dead		Remove
151	DC130	SE Main St	41-42	135	AF	T	12	Oak		Dead	Y	Remove
152	DC131	SE Main St	41-42	137	AF	T	23	Oak		Almost dead	Y	Remove
153	DC132	SE Main St	43-44	Lot	AF	T	20	Oak		Dead	Y	Remove
154	DC133	SE Main St	43-44	140		T	26	Pine		Weight over line, dieback, less than 40% crown		Remove
155	DC133	SE Main St	43-44	140		T	19	Oak		Heavy dieback	Y	Remove
156	DC134	SE Main St	45-46	Lot	AF	T	14	Birch		Almost dead		Remove
157	DC135	SE Main St	46-47	Lot		T	12	Pine		Weight over line, dieback, less than 30% crown		Remove
158	DC135	SE Main St	46-47	Lot		T	12	Pine		Weight over live, dieback		Remove
159	DC135	SE Main St	47-48	Lot		T	10	Pine		Weight over live, dieback		Remove
160	DC136	SE Main St	48-49	Lot		T	18	Pine		Wound at base, almost dead		Remove
161	DC136	SE Main St	48-49	Lot		T	24	Pine		Weight over lines, dieback		Remove
162	DC138	SE Main St	51-52	165		T	20	Oak		Heavy dieback, proximity	Y	Remove
163	DC138	SE Main St	51-52	165		T	10	Oak		Dead	Y	Remove
164	DC138	SE Main St	51-52	165		T	12	Oak		Dead	Y	Remove
165	DC139	SE Main St	53-54	171		T	15	Pine		Weight over line, proximity		Remove
166	DC140	SE Main St	55	172	AF	T	24	Oak		Dead	Y	Remove
167	DC140	SE Main St	55-56	172	AF	T	22	Oak		Dead	Y	Remove
168	DC141	SE Main St	55-56	176		T	16	Birch		Cavity at base with decay		Remove
169	DC142	SE Main St	57-58	Lot	AF	T	17	Oak		Lean, weight over line, dieback, cavity 8' up with decay	Y	Remove
170	DC142	SE Main St	57-58	Lot	AF	T	14	Birch		Dead		Remove

Ownership Key:
C/T = City or Town
P = Private
S = State
M = Municipal

Town of Douglas (Town and Municipal-owned Trees)

nationalgrid

Town of Douglas Enhanced Vegetation Management Tree Removal/Trim List Circuit #: 320W2										Gypsy Moth Damage - Insert		Work Proposed	
Count	Site ID	Street Name	Pole #	House #	Location	Owner	Dia.	Species	# Stem	Defect Condition			
171	DC142	SE Main St	57-58	Lot	AF	T	10	Maple		Top dead, cavity 5' up w/decay			Remove
172	DC142	SE Main St	57-58	Lot	AF	T	21	Oak		Lean, weight over line, dieback, cavity at base w/decay	Y		Remove
173	DC142	SE Main St	57-58	Lot	AF	T	18	Oak		Lean, weight over line, cavity 6' up w/decay	Y		Remove
174	DC142	SE Main St	57-58	Lot	AF	T	17	Oak		Weight to line, dieback	Y		Remove
175	PJ04	West St	8-9	Lot		T	26	Pine		Proximity/ poor structure			Remove
176	PJ06	West St	12-13	25	AF	T	36	Oak		Trim 14" branch over lines back to trunk/ proximity trim			Trim
177	PJ05	West St	12-13	Lot	AF	T	16	Oak		Proximity/ heavy lean			Remove
178	PJ05	West St	12-13	Lot	AF	T	12	Oak		Proximity/ heavy lean/ dead leads			Remove
179	PJ05	West St	12-13	Lot	AF	T	14	Oak		Proximity/ heavy lean			Remove
180	PJ05	West St	13-14	Lot	AF	T	20	Oak		Proximity/ lean to lines/ dead leads			Remove
181	PJ05	West St	13-14	Lot	AF	T	26	Oak		Proximity/ lean to lines/ dead leads			Remove
182	PJ08	West St	15-16	32		T	18	R. Maple	2	Proximity/ topped in the past			Remove
183	PJ10	West St	18-19	41	AF	T	22	Oak		Proximity/ heavy lean			Remove
184	PJ14	West St	28-29	66		T	20	Oak		Proximity/ lean to lines			Remove
185	PJ14	West St	28-29	68		T	36	R. Maple		Proximity/ lean to lines/ poor structure			Remove
186	PJ17	West St	33-34	78	AF	T	13	Cherry		Proximity/ dead leads			Remove
187	PJ17	West St	33-34	78	AF	T	14	Cherry		Proximity/ dead leads			Remove
188	PJ18	West St	33-34	80	AF	T	18	R. Maple		Proximity			Remove
189	PJ18	West St	33-34	80	AF	T	6	Cherry		Proximity			Remove
190	PJ18	West St	33-34	80	AF	T	7	Cherry		Proximity			Remove
191	PJ18	West St	33-34	80	AF	T	9	Cherry		Proximity			Remove
192	PJ19	West St	35-36	89		T	27	Oak		Proximity			Remove
193	PJ19	West St	35-36	89		T	24	Spruce		Proximity/ topped in the past			Remove
194	PJ20	West St	38-39	95		T	29	Oak		Proximity/ dead leads			Remove
195	PJ21	West St	39-40	98	AF	T	38	Oak		Proximity/ dead leads/ severe crown decline			Remove
196	PJ29	West St	45-46	120		T	19	Oak		Proximity			Remove
197	PJ34	West St	48-49	129	AF	T	24	Oak		Proximity/ dead leads			Remove
198	PJ35	West St	48-49	132	AF	T	16	Oak		Proximity/ dead leads			Remove
199	PJ35	West St	48-49	132	AF	T	29	Oak		Trim 10" branch over lines back to union			Trim
200	PJ35	West St	49-50	132		T	24	Oak		Proximity/ dead leads			Remove
201	PJ37	West St	51-52	134		T	11	R. Maple		Proximity/ internal decay			Remove

Ownership Key:
 C/T = City or Town
 P = Private
 S = State
 M = Municipal

Town of Douglas (Town and Municipal-owned Trees)

nationalgrid

Town of Douglas Enhanced Vegetation Management Tree Removal/Trim List Circuit #: 320W2										GYPSY MOTH DAMAGE - INSERT		Work Proposed	
Count	Site ID	Street Name	Pole #	House #	Location	Owner	Dia.	Species	# Stem	Defect Condition			
202	PJ37A	West St	51-52	137	AF	T	40	Oak		Proximity/ trim including 20" lead over lines back to trunk			Trim
203	PJ37A	West St	51-52	137	AF	T	40	Oak		Proximity/ trim including 20" lead over lines back to trunk			Trim
204	PJ39	West St	52-53	141	AF	T	38	Oak		Proximity/ dead leads			Remove
205	PJ41	West St	53-54	147		T	12	R. Maple		Proximity/ rotted cavity 10' up			Remove
206	PJ40	West St	54-55	164		T	12	Oak		Proximity/ poor structure			Remove
207	PJ40	West St	54-55	164		T	20	Oak		Proximity			Remove
208	PJ40	West St	54-55	164		T	22	Oak		Proximity			Remove
209	PJ42	West St	55-56	151		T	16	Ash		Proximity/ rotted wound at base			Remove
210	PJ40	West St	55-56	164		T	20	Oak		Proximity/ dead leads/ crown decline/ large wound at base internal decay/ poor structure/ lean to lines			Remove
211	PJ43	West St	56.5-57	2 Cross St	AF	T	13	Ash	3	Proximity/ snapped in half			Remove
212	PJ47	West St	64-65	7 Conservation Dr		T	30	Cherry		Proximity/ dead			Remove
213	PJ53	West St	68-69	205		T	12	Oak		Proximity/ dead leads			Remove
214	PJ51	West St	68-69	206	AF	T	28	Oak		Proximity/ dead			Remove
215	PJ51	West St	68-69	206	AF	T	24	Oak		Proximity/ damage at base			Remove
216	PJ53	West St	69-69.5	205		T	15	Ash	2	Proximity/ large rotted cavity at base internal decay/ hollow trunk			Remove
217	PJ53	West St	69-69.5	205		T	32	Ash		Proximity/ severe crown decline			Remove
218	PJ54	West St	69.5-70	209		T	19	Oak		Proximity/ dead			Remove
219	PJ55	West St	70-70.5	212		T	16	Oak		Proximity/ dead			Remove
220	PJ55	West St	70-70.5	212		T	24	Oak		Proximity/ dead leads/ crown decline/ rotted wound at base			Remove
221	PJ55	West St	70.5-71	212		T	28	Oak		Proximity/ dead leads			Remove
222	PJ58	NW Main St	74-43	4 Birch St		T	10	Oak		Proximity/ topped in the past			Remove
223	PJ58	NW Main St	74-43	4 Birch St		T	18	Oak	2	Proximity/ topped in the past			Remove
224	PJ58	NW Main St	74-43	4 Birch St		T	12	Pine		Proximity/ topped in the past			Remove
225	PJ58	NW Main St	74-43	4 Birch St		T	13	Oak		Proximity/ topped in the past			Remove
226	PJ59/PJ60	NW Main St	45-46	354/ 2 Cottage Colony		T	14	Oak		Proximity/ topped in the past			Remove
227	PJ64	NW Main St	47-48	25 Cottage Colony		T	25	Oak		Proximity/ dead branches			Remove

Ownership Key:
C/T = City or Town
P = Private
S = State
M = Municipal

Town of Douglas (Town and Municipal-owned Trees)

nationalgrid

Town of Douglas Enhanced Vegetation Management Tree Removal/Trim List Circuit #: 320W2										GYPSY MOTH DAMAGE - INSERT E ₁		Work Proposed
Count	Site ID	Street Name	Pole #	House #	Location	Owner	Dia.	Species	# Stem	Defect Condition		
228	PJ64	NW Main St	47-48	25 Cottage Colony		T	30	Oak		Proximity/ internal decay/ hollow trunk/ rotted cavity at base		Remove
229	PJ65	NW Main St	47-48			T	23	Oak		Proximity/ dead branches		Remove
230	PJ66	NW Main St	48-48.5			T	36	Oak		Proximity trim		Trim
231	PJ66	NW Main St	48.5-49			T	34	Oak		Proximity trim		Trim
232	PJ67	NW Main St	48.5-49			T	7	Ash		Proximity		Remove
233	PJ68	NW Main St	48.5-49	415		T	16	Oak		Proximity/ dead broken branches		Remove
234	PJ69	NW Main St	49-50	389		T	22	Oak		Proximity/ poor structure		Remove
235	PJ69	NW Main St	49-50	389		T	15	Oak		Proximity/ large rotted crack on front of trunk		Remove
236	PJ69	NW Main St	49-50	389		T	25	Hickory		Proximity/ large broken branch		Remove
237	PJ67	NW Main St	49-50	422	AF	T	37	Oak		Proximity trim		Trim
238	PJ72	NW Main St	50-51	464	AF	T	16	Ash		Proximity trim		Trim
239	PJ72	NW Main St	50-51	464	AF	T	14	Ash		Proximity/ large wound on base		Remove
240	PJ115	SE Main St	78-79	250		T	19	Ash		Proximity/ cavities/ dead leads		Remove
241	PJ115	SE Main St	78-79	250		T	18	Ash		Proximity/ broken, dead leads		Remove
242	PJ117	SE Main St	78-79	3 Pine St	AF	T	10	Ash		Proximity/ lean to lines/ wound at base		Remove
243	PJ117	SE Main St	79-80	3 Pine St	AF	T	21	Oak		Proximity/ dead		Remove
244	PJ118	SE Main St	80-81	4 Pine St	AF	T	15	Oak		Proximity/ dead, rotted branch at bend		Remove
245	PJ118	SE Main St	81	4 Pine St	AF	T	17	S. Birch		Proximity/ dead leads/ cavities throughout		Remove
246	MD01	Franklin St	2	3	AP	T	18	Maple		Proximity		Trim
247	MD04	Franklin St	8-10	20	AF	T	37	S. Maple		Overhang		Remove
248	MD05	Franklin St	19-20	lot		T	22	Cherry		Proximity		Remove
249	MD05	Franklin St	19-20	lot		T	16	Pine		Proximity		Remove
250	MD05	Franklin St	17-19	lot		T	14	Maple		Proximity		Remove
251	MD05	Franklin St	17-19	lot		T	14	Pine		Proximity		Remove
252	MD09	Franklin St	25-26	lot		T	20	Pine		Proximity		Remove
253	MD09	Franklin St	25-26	lot		T	18	Pine		Proximity		Remove
254	MD09	Franklin St	25-26	lot		T	18	Pine		Proximity		Remove
255	MD10	Franklin St	25-26	lot		T	16	Oak		Proximity		Remove
256	MD13AA	Franklin St	28-29	lot		T	36	Maple		Proximity		Remove
257	MD13AA	Franklin St	28-29	lot		T	38	Maple		Proximity		Remove
258	MD13A	Franklin St	29	lot	AP	T	8	Pine		Proximity		Remove
259	MD13A	Franklin St	29-30	lot		T	34	Maple		Proximity		Remove
260	MD13A	Franklin St	29-30	lot		T	12	Cedar		Proximity		Remove
261	MD14	Franklin St	30-31	lot		T	34	Maple		Proximity		Remove

Ownership Key:
 C/T = City or Town
 P = Private
 S = State
 M = Municipal

Town of Douglas (Town and Municipal-owned Trees)

nationalgrid

Town of Douglas Enhanced Vegetation Management Tree Removal/Trim List Circuit #: 320W2										GYPSY MOTH DAMAGE - INSERT		Work Proposed
Count	Site ID	Street Name	Pole #	House #	Location	Owner	Dia.	Species	# Stem	Defect Condition	Y	
262	DC143	South St	9-10	25		T	20	Oak		Lean, weight over line, proximity	Y	Remove
263	DC144	South St	11-12	30		T	25	Maple		Lean, weight over line, dieback		Remove
264	DC145	South St	13-14	Lot		T	18	Pine		Weight over line, proximity		Remove
265	DC145	South St	13-14	Lot		T	10	Pine		Weight over line, proximity		Remove
266	DC148	South St		53		T	27	Oak		Proximity, dieback	Y	Remove
267	DC151	South St	39-39/50	95		T	27	Oak		Lean, weight over lines, dieback, proximity		Remove
268	DC151	South St	39-39/50	95		T	15	Hickory		Dead	Y	Remove
269	DC151	South St	39/50-40	95		T	10	Pine		Almost dead		Remove
270	DC151	South St	39/50-40	95		T	18	Pine		Weight to line, dieback, proximity		Remove
271	DC151	South St	39/50-40	95		T	32	Oak		Dead	Y	Remove
272	DC151	South St	39/50-40	95		T	18	Maple		Lean, weight over lines, dieback, proximity		Remove
273	DC154	South St	41/50-42	109		T	28	Pine		Weight over line, dieback		Remove
274	DC154	South St	42-43	108	AF	T	22	Oak	2	Dead	Y	Remove
275	DC155	South St	41/50-42	112		T	12	Oak		Dead	Y	Remove
276	DC155	South St	41/50-42	112		T	14	Oak		Lean, weight over line, heavy dieback	Y	Remove
277	DC155	South St	41/50-42	112		T	24	Oak		Lean, weight over line, heavy dieback	Y	Remove
278	DC155	South St	42-43	112		T	17	Oak		Proximity	Y	Remove
279	DC155	South St	41/50-42	112		T	13	Oak		Dead	Y	Remove
280	DC155	South St	42-43	112		T	24	Oak		Dead	Y	Remove
281	DC155	South St	42-43	112		T	8	Pine		Proximity		Remove
282	DC156	South St	43-44	114		T	18	Birch		Dead		Remove
283	DC157	South St	44-44/50	116		T	18	Ash		Dead		Remove
284	DC158	South St	44/50-45	117	AF	T	20	Oak		Dead	Y	Remove
285	DC158	South St	44/50-45	117	AF	T	20	Oak	2	Lean, weight to line, dieback	Y	Remove
286	DC158	South St	45-46	117	AF	T	32	Oak		Lean, weight to line, almost dead	Y	Remove
287	DC158	South St	45-46	117	AF	T	27	Oak		Lean, weight to line, almost dead, cavity with decay	Y	Remove
288	DC158	South St	45-46	117	AF	T	28	Oak		Lean, weight to line, almost dead, cavity with decay	Y	Remove
289	DC158	South St	45-46	117	AF	T	32	Oak		Lean, weight to line, almost dead, cavity with decay	Y	Remove
290	DC160	South St	45-46	123	AF	T	15	Oak		Lean, weight to line, cavity with decay	Y	Remove

Town of Douglas
(Town and Municipal-owned Trees)

national **arid**

[illegible]